













- LEGEND**
-  Tree Position with canopy spread, Category A
 -  Tree Position with canopy spread, Category B
 -  Tree Position with canopy spread, Category C
 -  Tree Position with canopy spread, Category U
 -  Tree(s) to be removed for construction
 -  Root Protection Area (RPA) according to BS5837:2012
 -  Location of Protective Fencing
 -  Location of Protective Fencing - Set back
 -  Construction Entrance
 -  Material Storage / Contractors Parking
 -  Construction Exclusion Zone (CEZ)



DRAWING NOTES:

OS Base Plan supplied by Client
Do not scale from this drawing

Document Version		
REV	Description	Date
1	Draft issue v1 - for design purposes	05.01.2023
2	Issue for planning	20.07.2023
3	Access removed, contours	22.08.2023

PROJECT:
Streetly Hall Farm - AD Plant

DRAWING TITLE / SHEET No:
Tree Asset Plan - 1

DATE: 22.08.2023 DRAWN BY: JS

PROJECT REF: 2022.095.1 DRAWING NO. 1 of 1

SCALE: 1:2500@A1



NORFOLK WILDLIFE SERVICES

Norfolk Wildlife Services
22 Thorpe Road,
Bewick House
Norwich
NR1 1RY
office@norfolkwildlifeservices.co.uk
01603625540